



PECFA number: 53916-2331-01
BRRTS number: 03-14-170409
Site Owner: Wilmer Fuiten
Site Name: Beaver Dam Fuel Service Center
Site Address: 201 S. Spring Street, Beaver Dam, WI

Program contact: Mark F. Putra - DNR Hydrogeologist
Program contact address: N7725 STH 28, Horicon, WI 53032
Program contact phone: (920) 387-7867

Submitted Questions and Responses

1. Are we allowed to call subcontractors in order to get some hypothetical costs?

Yes, you may contact subcontractors.

2. ...the site investigation report referenced an Underground Storage Tank Closure Assessment Report dated January 1999 that was not included with the site assessment report. In order to submit this bid, we need to obtain a copy of that Underground Storage Tank Closure Assessment Report. How can we go about doing that?

If you wish to view the file in my office, then you may review the DNR project file by contacting me by telephone at my office.

3. Will you require a deeper piezometer to be installed on site?

NO

4. Will an additional well downgradient of MW-6 be required?

NO

4. Is the City of Beaver Dam well #3 impacted?

No, and this matter has been discussed with the staff member of the DNR Bureau of Drinking Water assigned to the City of Beaver Dam, and the municipal well will not need to be tested as part of the remediation project. The municipal well has a total depth of 585 feet, and the protective casing extends to 315 feet.